United States Department of the Interior Heritage Conservation and Recreation Service

National Register of Historic Places Inventory—Nomination Form

received date entered

For HCRB use only

BA-30

See instructions in *How to Complete National Register Forms*Type all entries—complete applicable sections

Type un entires	complete appl	TOUDIC 3C	CUOIIS					
1. Nam	ie							
historic	Church o	Church of St. Mary the Virgin (Protestant Episcopal)						
and/or common	St. Mary	St. Mary's Episcopal Church, Woodlawn (preferred)						
2. Loca	ation							
street & number	5610 Dog	wood Roa	ıd			n/a not for publication		
city, town	Woodlawn		X vicinity of		congressional district	Seventh	Seventh	
state	Maryland	code	24	county	Baltimore	code	005	
3. Clas	sificatio	n						
Category district building(s) structure site object	Ownership public X private both Public Acquisit in process being consid X not applic	dered	Status _X_ occupi unoccu work in Accessible _X_ yes: re yes: un	upied n progress e estricted	Present Useagriculturecommercialeducationalentertainmentgovernmentindustrialmilitary	museu park private X religiou scienti transp	residence us fic	
4. Own	er of Pro	pert	ty					
name	Vestry o	f St. Ma	ry's Epis	scopal Ch	urch			
street & number	5610 Dog	√ood Roa	ıd					
city, town	Woodlawn		n/a vic	inity of	state	Maryland	21207	
5. Loca	ation of I	Lega	Des	criptic	on			
courthouse, regis	stry of deeds, etc.	Baltin	ore Count	y Courth	ouse			
street & number								
city, town		Towson	:		state	Maryland	21204	
6. Repr	esentat	ion i	n Exis	iting \$	Surveys			
Maryla	and Historical cory of Histor	Trust			perty been determined e			
depository for sur	rvey records	21 Sta	te Circle					
city, town	···	_Annapo	lis		state	Maryland	21401_	

7. Description			BA-30	
Condition excellent	deteriorated	Check one	Check oneX_ original site	

fair	ruins unexposed	A altered	moved	daten	/a	

Describe the present and original (if known) physical appearance

Number of Reso	urces	Number of previously listed			
Contributing	Noncontributing	National Register properties			
1	0 buildings	included in this nomination: 0			
0	0 sites				
0	0 structures	Historic Function: religious			
0	O objects	1011010			
1	O _Total				

DESCRIPTION SUMMARY:

St. Mary's Episcopal Church, Woodlawn, is a frame Gothic structure designed by the Baltimore architectural firm of Dixon and Carson and constructed in 1873 near Woodlawn, a streetcar suburb of Baltimore City. The church is rectangular, with a steeply-pitched gable roof, and faces south; the principal facade is five bays wide, with a two-bay-wide chancel extending from the east gable. The entrance is located in a gabled vestibule projecting from the westernmost bay. A small open belfry rises from the east gable peak. A three-part composition of lancet windows lights the west gable, and a rose window pierces the east; all openings are lancet arched, and windows are of stained and etched glass. A modern parish hall adjoins the church on the northeast. The interior remains largely intact, and the building possesses a high degree of integrity.

For General Description, see Continuation Sheet No. 1

OMB No. 1024-0018 Exp. 10-31-84

1

United States Department of the InteriorNational Park Service

National Register of Historic Places Inventory—Nomination Form

Continuation sheet St. Mary's Episcopal Church, Woodlawn Baltimore County, Maryland Item number

BA-30
For NPS use only
received
date entered

Page

7

GENERAL DESCRIPTION:

St. Mary's Episcopal Church is a board-and-batten frame Gothic parish church constructed in 1873 near Woodlawn in Baltimore County, Maryland. Designed by the Baltimore architectural firm of Dixon and Carson, the church reflects the influence of Richard Upjohn's 1850 publication, Rural Architecture. It is composed of a rectangular nave, five bays wide, which faces south under a high, steep gable roof; a lower, two-bay-wide chancel extends from the east end. The entrance is located in the westernmost bay, consisting of a small vestibule with a steeply-pitched gable roof; double-leaf doors with ornate iron strap hinges are set within a lancet-arched opening. The remaining bays are defined by lancet-arched stained glass windows. The west gable features a group of three tall lancet-arched windows of clear etched glass with colored borders. The chancel is lighted by a rose window in the east gable.

Interior walls are finished in plaster above narrow vertical beaded wainsceting which rises to the level of the window sills. The windows are framed with simple two-part architraves. Interior doors (one leading in from the vestibule, and one opening from the easternmost bay of the north wall into the vestry room) are rectangular and double-leafed; each leaf has two oblong panels, one above the other, and they are set within a lancet-arched opening with similar paneling filling the peak. Square engaged posts define the interior bays, rising to decorative rafter trusses (the ceiling was dropped to the level of the collar beams in a c.1945 renovation). The pews in the sanctuary are modern, but original pews survive in the choir stalls flanking the chancel.

The chancel flooring is edged with several bands of alternating light and dark one-inch hardwood. Choir stalls on either side of the chancel are defined by open lancet arcade screens above waist-high wainscot partitions.

In 1954, a low, gable-roofed frame wing was constructed against the east end of the chancel, with a shed-roofed extension on its north side connecting it with the vestry room. This addition serves as a parish hall. As most of the structure is hidden by dense evergreens at the rear of the church, it has minimal visual impact.

The church retains considerable integrity. Apart from the parish hall wing, the only alteration is the recent (summer 1984) installation of synthetic siding. In planning, the Vestry was concerned that this alteration be reversible, and involve the minimum practicable damage to the historic fabric of the building. Siding imitating vertical boards was chosen to reproduce as closely as possible the visual effect of the original board and batten. In addition, the installation was carried out so that the original fabric would remain unharmed, by placing styrofoam insulating panels between the existing battens,

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

BA-30

For NPS use only

received

date entered

Continuation sheet

St. Mary's Episcopal Church, Woodlawn Baltimore County, Maryland Item number

7

Page

2

GENERAL DESGRIPTION (continued)

creating a flush surface for the attachment of the new siding. Decorative elements such as window frames were carefully covered. The most unfortunate results are the enclosure of part of the belfry formerly expressed as intricate, open framing, and the sheathing of the eaves, obscuring decorative purlin ends like those which remain exposed on the vestibule. These changes, however, are reversible, and the basic form and proportions of the building remain clearly apparent.

Period prehistoric 1400–1499 1500–1599 1600–1699 1700–1799X 1800–1899 1900–	Areas of Significance—C archeology-prehistoric agriculture architecture art commerce communications	community planning conservation economics education	landscape architectur law literature music	e religion science sculpture social/ humanitarian theater transportation other (specify)
Specific dates	1873	Builder/Architect	Dixon and Carson, arc	hitects

Statement of Significance (in one paragraph)

Applicable Criteria: C
Applicable Exceptions: A
Significance Evaluated: local

SIGNIFICANCE SUMMARY:

St. Mary's Episcopal Church, Woodlawn, is significant for its architecture, exemplifying the influence of the Gothic Revival on the design of rural frame churches in the third quarter of the nineteenth century. One of fewer than ten surviving churches in Maryland whose construction, form, proportions, and detailing recall patterns published in Richard Upjohn's <u>Rural Architecture</u>, St. Mary's derives additional significance from its association with the prominent Baltimore architectural firm of Dixon and Carson, to whose design it was constructed in 1873. This modest frame building is atypical of the work of this firm which was more commonly identified with imposing stone Gothic churches in urban Baltimore in the 1870s.

United States Department of the InteriorNational Park Service

National Register of Historic Places Inventory—Nomination Form

BA-30 For NPS use only

received

date entered

Continuation sheet St. Mary's Episcopal Church, Woodlawn
Baltimore County, Maryland Item number

8

Page

- 3

HISTORY AND SUPPORT:

St. Mary's Episcopal Church, Woodlawn, is one of fewer than ten examples surviving in Maryland of rural frame churches whose design shows the influence of Richard Upjohn's 1850 publication, Rural Architecture. Although its board-and-batten siding was recently covered with synthetic material, the church retains the rectangular form, vertical proportions, and Gothic detailing which Upjohn espoused for small churches serving rural congregations. The interior also remains almost completely intact, and features unusual lancetarched screens defining the choir stalls.

Baltimore architects Thomas Dixon (AIA 1870) and Charles L. Carson (1847-1891; AIA 1871) formed a partnership in the 1870s. The firm designed several commercial buildings in Baltimore including the Fireman's Fund Insurance Building and the old American Building (completed 1876, destroyed in the fire of 1904), but is perhaps most noted for its large stone Gothic urban churches: Mount Vernon Place Methodist Church (1873; National Register), Eutaw Place Presbyterian Church (1879), Northminster (Boundary Avenue) Presbyterian Church (1879), and Lafayette Square Presbyterian Church (now St. John AME Church, 1880). In its then-rural setting, frame construction, modest size and simplicity, St. Mary's is quite unlike Dixon and Carson's other known ecclasiastical commissions, and the comparison reveals the firm's wide-ranging competence. St. Mary's is more similar to the Mount Washington Presbyterian Church (1878), a board-and-batten Gothic building designed by Thomas Dixon in that burgeoning railroad suburb of Baltimore.

"The history of St. Mary's Church of Woodlawn began in the year 1870 in Powhatan-Franklintown area of Baltimore County where a young woman, ill with a terminal disease, asked that Episcopal rites be administered to her. Although at that time no Episcopal Church existed in the community, the Reverend Mr. William A. Coale, an assistant clergyman from St. Lukes Church in Baltimore City, was brought to her. Holy Communion was administered and hymns were sung. This constituted the first Episcopal service held in the neighborhood.

"After this, services were started in the Franklintown Inn in February, 1872. In the fall of 1872, Sunday School was begun and then, in January of 1873, a meeting was held to discuss the building of a church. Land was donated by Mr. William P. Webb. Ground was broken in February, 1873; the cornerstone was laid in April 1873; and the opening service took place in October, 1873."

The April 20, 1873 issue of the <u>Maryland Journal</u> provides an account of the cornerstone-laying ceremonies which includes a description of the church:

The main building is to be 60 feet deep and 24 feet wide, and a vestry 14 by 9. The building will be frame, painted a light drab color, covered with a shingle roof, and adorned with stained glass windows. The style of the architecture is gothic. The Church is being erected under contract by Messrs. Barnes and Taylor, Dixon and Carson, architects.

The cost of construction was estimated between six and seven thousand dollars.

See Continuation Sheet No. 4

4

3A-30

United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received

Continuation sheet St. Mary's Episcopal Church, Woodlawn Baltimore County, Maryland Item number

Page

date entered

HISTORY AND SUPPORT (continued)

"The Reverend Mr. William A. Coale was the first priest. Two other full-time priests followed: The Right Reverend Mr. Charles R. Hale and the Reverend Mr. J. Pinkney Hammond.

'In 1881, after the departure of the second full-time priest, the church, whose congregation had remained small, became unable to meet payment on its loan and mortgage foreclosure was threatened. However, the Bishop proposed that each member contribute \$10.00 to forestall the closing of the church. This helped to meet the immediate need. Other funds were raised and the debt was paid in full in 1886. Although the church was consecrated in that year (1886), no full-time clergy was obtained until 1913. Then the Reverend William Rollins Webb, whose father had donated the land for the church, became priest at St. Mary's. After he left in 1923, mission priests and lay readers kept the parish alive although there was very little activity during this period of time.

"In the year 1932, the Reverend Mr. J. George Carl became associated with the church and held services for those who still maintained an interest, although these services were not held on a regular basis. No real growth was in evidence, however, and in 1949 there were only seven families consisting of sixteen persons who still maintained an interest in the church. In that year a core of young men undertook to rebuild the church, which was now suffering from many years of neglect and deterioration. A part of the sacristy roof had collapsed and it was considered unsafe to use this part of the church. Work progressed with direction and support from the Reverend Mr. Carl.

"Lay leaders on the rebuilding project were Mr. Richard Heacock, Mr. Robert Heacock, his brother, and Mr. Harry W. Leutner, Jr. Others contributed in physical labor and monetary gifts to restore the church. The Vestry, Ladies Guild and Sunday School were maintained and grew during the years following 1949.

"In 1954 the Parish House was completed and dedicated.

"The Reverend Paul Dawson, in the year 1957, became the first full-time priest in many years. Then, in July 1959, the Reverend John Rollman was called to the church on a full-time basis. Activities and membership increased under his leadership. In 1962, six and a half acres of woodland were purchased across the road from the church. The 90th anniversary of the church was celebrated in September, 1963. An active Youth Group was organized during this time.

United States Department of the Interior

National Park Service

National Register of Historic Places Inventory—Nomination Form

BA - 30

For NPS use only

received

date entered

St. Mary's Episcopal Church, Woodlawn

Continuation sheet Baltimore County, Maryland Item number 8, 9 and 10

Page

5

HISTORY AND SUPPORT (continued)

"The tenure of the Reverend William Fallowfield began in 1967 and continued until 1974. The Centennial Celebration held in 1973 was considered to be a very successful venture. Over \$5,000 in capital funds was raised by means of the Centennial Plaque which now hangs at the back of the church, and by other activities surrounding this event. A month-long program of services and special events was held.

"After the Reverend Fallowfield left the church to become a leader at the Claggett Center, the Vestry again took up the search for a priest for the membership, but it was felt that a full-time minister was not warranted. The Reverend Joseph Clark was engaged on a part-time basis in 1974 and in 1976, The Reverend David W. Cammack became St. Mary's second worker priest, serving until 1983 when he announced his plan to accept another calling. During the Reverend Cammack's term of service, the new Book of Common Prayer came into usage; ecumenical services were held in conjunction with three neighboring churches; and new music was introduced into the church. The music was in the form of new hymnals (Songs of Praise) and the use of guitars during the service."2

In 1984, the Reverend Bob Butehorn assumed the rectorship.
1 Leutner, M. "A Brief History of St. Mary's Church of Woodlawn" ms., 1984. 2 Ibid.

MAJOR BIBLIOGRAPHICAL REFERENCES:

Dorsey, John, and James D. Dilts. A Guide to Baltimore Architecture. (Centreville, MD: Tidewater Publishers, 2nd ed., 1981).

Hunter, Wilbur H., Jr. and Charles H. Elam. Century of Baltimore Architecture. (Baltimore: The Peale Museum, 1957).

Leutner, M. "A Brief History of St. Mary's Church of Woodlawn," ms. 1984 on file at Maryland Historical Trust.

Maryland Journal, Towson, MD., April 20, 1873, p. 3.

Maryland Architects vertical files, Maryland Historical Trust, Annapolis.

GEOGRAPHICAL DATA:

Verbal boundary description and justification: The nominated property, approximately 0.7 acre, represents the lot on the north side of Dogwood Road historically associated with the church. Other property across the road, acquired by the church in 1962, does not contribute to the significance of the resource and is not included in the nominated acreage. Boundaries are depicted on the attached plot plan.

See Continuation Sheet No. 5

10. Geo	graphical D	ata		
Acreage of nomina Quadrangle name UMT References	ated property approxima Baltimore West, Ma	ately 0.7 acrearyland		Quadrangle scale1:24000
Zone Easting	6 11 10 4 13 5 12 7 1 Northing	210		sting Northing
G		F		
Verbal boundary	y description and justific	ation		
See Cont	inuation Sheet No. 5	5		
List all states a	nd counties for propertic	es overlapping st	ate or count	ty boundaries
state n/a	cod			code
state	cod	e county		code
11. For	m Prepared	Ву		
name/title	Peter E. Kurtze, A	Accietant Natio	nal Ragic	ter Administrator
			mar Regis	
organization	Maryland Historica	al Irust	date	October 1984
street & number	21 State Circle		teleph	one (301) 269-2438
city or town	Annapolis		state	Maryland 21401
12. Stat	te Historic P	reservat	ion Of	ficer Certification
_	ificance of this property wit	thin the state is: $-\frac{X}{}$ local		
665), I hereby nomi	State Historic Preservation inate this property for inclusive iteria and procedures set for iteria and iteria and	sion in the National	Register and	Preservation Act of 1966 (Public Law 89– certify that it has been evaluated and Recreation Service.
State Historic Pres	ervation Officer signature	M	uffer	
title	STATE HISTORIC PR	ESERVATION OFF	ICER	date 1-31-85
For HCRS use on I hereby certi	iy fy that this property is inclu	ided in the National	Register	
		San The Carlo		date
Keeper of the Na	tional Register			
Attest:			· .	date
Chief of Registrat	ion			

Maryland 1. STATE Baltimore COUNTY

TOWN Franklintown VICINITY STREET NO. Dogwood Road

Dist. I

HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY BA-30

St. Mary's Episcopal Church 2. NAME

1873 DATE OR PERIOD STYLE

ARCHITECT BUILDER

3. FOR LIBRARY OF CONGRESS USE

ORIGINAL OWNER ORIGINAL USE PRESENT OWNER PRESENT USE WALL CONSTRUCTION NO. OF STORIES

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC

Picturesque Victorian style church, shaded by old trees, near entrance to Lorraine Cemetery; steeply slanting roof, frame (board and batten) painted white with dark green trim; very narrow elongated stained glass windows.

5. PHYSICAL CONDITION OF STRUCTURE Endongered

Interior

Exterior



6. LOCATION MAP (Plan Optional)


3. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.

7. PHOTOGRAPH

9. NAME, ADDRESS AND TITLE OF RECORDER (First HABS Report) E. Frances Offutt HABS COMMITTEE OF BALTIMORE COUNTY HISTORICAL SOCIETY

DATE OF RECORD

July 29, 1965




TSCALE IN ESON

ST. MARYS EPISCOPAL CHURCH.

DOGWOOD ROAD.

BALTO, COUNTY. MD.





St. Mary's Episcopal Church, Woodlawn
Baltimore County, Maryland
Peter E. Kurtze, August 1984
negative at Maryland Historical Trust
view from southwest
1/4




St. Mary's Episcopal Church, Woodlawn BA-30 Baltimore County, Maryland Peter E. Kurtze, August 1984 negative at Maryland Historical Trust interior, facing northeast 2/4



St. Mary's Episcopal Church, Woodlawn BA-30
Baltimore County, Maryland
Peter E. Kurtze, August 1984
negative at Maryland Historical Trust
interior, facing west
4/4



St. Mary's Episcopal Church, Woodlawn BA-30
Baltimore County, Maryland
Peter E. Kurtze, August 1984
negative at Maryland Historical Trust
interior, facing southeast
3/4



BA-30 ST. MARY'S CHURCH WOODLAWN, BAUTO, CO., MD PETER KURTZE, 2/84 VIEW PROM SOUTHWEST